#### Method of Test for Determining the Cutout Correction and In Place Density of Asphalt Concrete by the Nuclear Gauge Method

#### 1. Scope:

This test is for determining the in place density of asphalt concrete by using the nuclear gauge. A correction needs to be applied to the nuclear gauge to obtain an accurate in place density. A gauge reading will be taken at the cutout or core site prior to the removal the asphalt concrete. The density of the cutout or core will then be determined.

#### Definitions:

<u>Standard Density:</u> Average of the 5 most recent theoretical maximum specific density determinations.

<u>Lot:</u> A quantity of material from a single source, representing a specific segment of construction, upon which decision is made for acceptance.

Random Measurement: A specific individual measurement of in place density (One of 5 measurements made for a lot), the location is chosen such that each portion of the lot has an equal probability of being selected.

#### 2. Apparatus:

- 2.1 Scale or balance having the capacity to weigh any sample which may be tested utilizing this procedure and readable to the nearest 0.1 gram. The scale or balance will be equipped with a suitable suspension apparatus and holder to permit weighing the sample while suspended from the center of the scale pan of the weighing device.
- 2.2 The water bath for immersing the sample will be equipped with an overflow outlet for maintaining a constant water level. An aquarium heater will suffice to control the temperature of the water bath at 77° ± 2° F. The water bath must be large enough to allow the suspension apparatus holder to be covered with water at all times. The sample and suspension apparatus must be completely covered with water during weighing. The wire suspending the suspension apparatus will be the smallest practical size to minimize any possible effects of a variable immersed length.
- 2.3 A thermometer with subdivisions and maximum scale error of 1°F to cover the range of testing.
- 2.4 Power-driven masonry saw capable of cutting a 6" x 6" compaction sample or a coring device capable of cutting a 6" diameter core from the pavement. Furnished and operated by Contractor.

#### Page 2

- 2.5 Miscellaneous. Pails, pans, hammer, roofing tacks, aluminum foil or pavement marking tape, spray paint, 50' tape measure, 1" x 2" x 12" stakes.
- 2.6 Nuclear moisture-density gauge capable of determining densities by the backscatter method and conforming to the requirements of AASHTO T 310.
- 2.7 A reference standard block for taking standard counts.
- 2.8 A manufacturer's instruction manual for the nuclear gauge.
- 2.9 A nuclear gauge logbook with transportation documents, and dosimeter.

#### 3. Procedure:

3.1 Calibration and Standardization of Nuclear Gauge.

#### A. Calibration

- (1) The Central Laboratory will calibrate nuclear gauges annually and each time repairs are made.
- B. Standard Count Troxler Model 3440
  - (1) Turn the gauge on and allow the gauge to warm up for at least 10 minutes.
  - (2) Place the gauge on the reference standard block and take the standard count as recommended by the manufacturer.
  - (3) Take at least one 4 minute standard count daily. This count should compare within 1% of the average of the 4 previous standard density counts and compare within 2% of the average of the 4 previous standard moisture counts for the gauge. If the standard count varies by more than these tolerances, do not accept the standard count. Check that all the manufacturer's guidelines have been followed and take another standard count.

NOTE: If the second count also fails, follow the manufacturer's recommendation for the particular model gauge for taking and recording 4 additional standard counts.

- (4) Record the results of the standard count in the gauge's logbook.
- C. Standard Count Troxler Model 4640-B
  - (1) Turn the gauge on and allow the gauge to warm up for at least 10 minutes.

- (2) Place the air gap spacer on the Magnesium (Mg) reference block and then place the gauge on top of the spacer. Take the 4 minute standard count as recommended by the manufacturer.
- (3) Take at least one standard count daily. The results will be compared with the average of the 4 previous standard counts for the gauge. The system 1 count should compare within 1.0% and the system 2 within 1.2%. If the standard count varies by more than these tolerances, do not accept the standard count. Check that all the manufacturer's guidelines have been followed and take another standard count.

NOTE: If the second count also fails, follow the manufacturer's recommendation for the particular model gauge for taking and recording 4 additional standard counts.

(4) Record the results of the standard count in the gauge's logbook.

#### 3.2 Compaction Sample Test Sites

- A. Randomly select test sites. The compaction samples will be representative of the lift thickness. A minimum of 3 compaction samples will be obtained per lift.
- B. Tack a double layer of aluminum foil or pavement marking tape, approximately 12" x 18" in size, to the base with roofing nails at each test site. There will be 3 compaction sample sites plus a backup for each lift. The backup will be cut or cored if one of the three samples is damaged.
- C. Mark the location of the foil or tape by measuring from the center of the foil or tape to 2 offset stakes and recording the distance.
- D. After the asphalt concrete has been placed and compacted, locate the foil by measuring the recorded distance from each stake and swinging arcs.

#### 3.3 Compaction Sample Density

A. Just prior to obtaining the compaction samples from the road, take 3 nuclear wet density readings in backscatter mode. Place the gauge near the middle of the test site and make sure that it doesn't "Rock" or shift due to an uneven surface. Keep the gauge turned parallel with the direction of travel of the paver and rollers. Lower the handle to the first notch, being careful not to pass the proper position and take a 1 minute reading to determine the wet density. Move the gauge approximately 3 inches perpendicular to the direction of travel and take the second reading. Move the gauge approximately 6 inches in the opposite direction and take the third reading.

Note: When using the Troxler 4640-B, you must enter into the gauge the asphalt concrete thickness minus  $\frac{1}{4}$  inch.

- B. Record the 3 wet density readings to the nearest 0.1 lbs./ft³ in the Cutout/Core Correction section on form DOT-42 and determine the average of the 3 wet densities at each compaction sample location.
- C. The Contractor will cool, saw and remove a 6" square sample or a 6" diameter core sample from the area designated. Check the sample closely for damage caused during removal.
- D. Immediately upon removal from the pavement, place the samples with the finished side down in a clean pan and place in a level position away from exposure to heat or other damaging conditions. As soon as sampling has been finished, transport the samples to the laboratory for the density determination. When the samples arrive at the field laboratory, place on a clean surface.
- E. Perform the following steps and record on DOT-42Q.
  - (1) Weigh the core and record the apparent dry weight in air to the nearest 0.1 gram on line (B).
  - (2) Immerse each specimen in water at 77° ± 2° F for 3 to 3 1/2 minutes and record the submersed weight to the nearest 0.1 gram on line (C).
  - (3) Remove each specimen from the water and surface dry by blotting with a damp terry cloth towel. Weigh and record the saturated surface dry (SSD) weight in air to the nearest 0.1 gram on line (D).
  - (4) Calculate the volume of the core (D C). Record on line (E).
  - (5) Record the pan number on line (F).
  - (6) Record the weight of the pan to the nearest 0.1 gram on line (G).
  - (7) Place the core in the pan and place in an oven at  $230^{\circ} \pm 9^{\circ}$  F for 2 hours, record the initial time.
  - (8) After the 2 hour period, record the weight of the core and the pan to the nearest 0.1 gram on line (J), record the time of weighing.
  - (9) Place the core and pan back in the oven and weigh at 1 hour intervals until the core has reached a constant weight. Constant weight is attained when the weight loss is within 0.1 percent of the apparent dry weight. Calculate the amount of

- allowable loss (B  $\times$  0.001) to the nearest 0.1 gram. Record on line (M).
- (10) After a constant weight has been attained, cool the pan and core to room temperature. Record the weight to the nearest 0.1 gram on line (N).
- (11) Determine the actual dry weight of the core (N G). Record on line (H).
- (12) Determine the core bulk specific gravity (H / E) to the nearest 0.001. Record on line (I).
- (13) Determine the moisture in the core (D H). Record on line (K).
- (14) Calculate the percent water absorbed by volume (K / E x 100) to the nearest 0.1 percent. Record on line (L).
- F. Compare the average of the 3 wet densities determined by the nuclear gauge to the average density determined by the 3 compaction samples. When the nuclear gauge average is <u>greater</u> than the compaction sample average, the correction will be <u>subtracted</u> and when the nuclear gauge average is <u>less</u>, the correction will be <u>added</u> to the wet density determined by the nuclear gauge. (Figure 2)

#### 3.4 Standard Density.

- A. The standard unit weight will be determined by the theoretical maximum specific gravity method in accordance with SD 312 (Figure 2).
  - (1) The average of the 5 most recent standard unit weight determinations will be used as the standard density.
  - (2) Until 5 standard unit weight determinations have been made, base the standard density on the first determination, then on the average of the first 2, 3, 4, and 5 determinations. Each standard density thereafter will be the average of the 5 most recent valid standard unit weight determinations and will be used when the same source, mix and plant are being used on one or more projects.
- 3.5 Selecting Density Test Locations.
  - A. Record the location of the lot to be tested by indicating Sta. to Sta. and the distance right or left of the centerline. Show the length, width, and quantity represented by the lot.

- B. Select 5 sites within the lot by use of the random number table. (Figure 1)
  - (1) Determine and record each site for the lot being tested to the nearest foot.
  - (2) The procedure for using the random number table is as follows:

Assume the lot to be tested is from Sta. 25+00 to Sta. 45+00 and extends from 12' left to centerline. The length of the lot is then 2000' and the width is 12'. Randomly select a number from the random number table.

- (3) Stationing of each site is determined by multiplying each random number by 2000' then adding the resulting distances to the beginning station.
- (4) Distance from centerline for each site is determined by multiplying each random number by 12'.

Measurement Site	Longitudinal distance	Transverse distance
1	2000 x 0.43 = 860	12 x 0.75 = 9.0
2	2000 x 0.85 = 1700	12 x 0.02 = 1.0*
3	2000 x 0.50 = 1000	12 x 0.40 = 4.8
4	2000 x 0.80 = 1600	12 x 0.14 = 1.7
5	2000 x 0.90 = 1800	12 x 0.47 = 5.6

- \* The transverse distance for site 2 was actually 0.24; however, transverse measurements falling closer than 1.0' to the edge are moved to 1.0' from the edge.
- C. Pacing longitudinal distances from station stakes or other known references and tape measurements of the transverse distances will be acceptable.
- D. When compaction has been completed and the lot is ready for testing, locate the selected test sites. The selected sites will not be marked, or their location revealed before the material represented by the lot is compacted and ready for acceptance testing (Figure 2).
- 3.6 In place density.
  - A. Base the density of the in place material on the average of random measurements made at pre-selected sites within the lot.
  - B. Set the gauge on each test site with the gauge parallel to the direction of travel of the paver and rollers. Ensure that the gauge does not rock. The gauge base must be completely in contact with the asphalt

material. Small shifts in the site locations necessary for proper seating of the gauge are permissible. Take a 1 minute wet density reading in the backscatter mode and record the results. Rotate the gauge 180 degrees and take a 2<sup>nd</sup> reading in the backscatter mode. Average the two results.

Note: When using the Troxler 4640-B, you must enter into the gauge the asphalt concrete thickness minus ½ inch.

C. Record the wet density to the nearest 0.1 lb./ft³ on the DOT-42.

#### 4. Report:

- 4.1 Calculations Nuclear Gauge Correction.
  - A. Calculate the cutout/core density (PCF) in lbs./ft³ from numbers recorded on DOT-42Q in the cutout calibration check on the DOT-42 in the following manner.

Weight of water  $(77^{\circ} F) = 62.245 \text{ lb./ft}^{3}$ 

H = Actual dry weight.

D = Saturated surface dry weight (SSD) in air

C = Submersed weight in water

Cutout/Core Density =  $H / (D - C) \times 62.245$ 

B. Calculate the Correction as follows:

Correction in lb./ft³ = Cutout/Core average – Nuclear Gauge average

- 4.2 Calculations Percent of Standard Density
  - A. Calculate the percent of standard density for each random measurement as follows:

Percent of Standard Density = Wet density lb./ft³ ± correction lb./ft³ x 100
Standard density

- B. Record the percent of standard density for each random measurement to the nearest whole percent.
- C. Calculate the percent of standard density for the lot by averaging the 5 random measurement percents of standard as recorded and report to the nearest whole percent.
- 4.3 Report the test as being satisfactory, provided all of the following conditions are met for each lot:

## **SD 311** Page 8

- A. The percent of standard density obtained for the lot is equal to or greater than that specified for the project.
- B. No more than 2 tests below specification.
- C. No more than 1 test that is 2% below specification.
- D. No tests that are 3% or more below specification.

#### 5. References:

AASHTO T 310 SD 312 DOT-42 DOT-42Q

21




Figure 1

SD 311 Page 10




Figure 1A

# Sample ID: 2311051 Density Report Bituminous Surfacing

**DOT-42** 3-19

PROJ	ECT P	H 0066(	00)15	COU	NTY Au	ora, Zieba	ıch			····g	•			PCN	B015
Test N	No.	04		Class a	nd Type	Class E A	Asphalt C	oncre	te	Lift	(	of	Thickness	5	
% As	ohalt Bind	ler	_		Actual	Finished \	Vidth	12.5	0 :	Station					
Teste	d By	Teste	r, One		Test Da	te 04/1	5/2020		Checked	Ву	Tester	, Two		-	
Speci	fication R	equirem	ents -	% of Star	ndard Re	quired	92	Min.					•		
Nuclear Density Gauge Data															
	Daily Che	eck Gau	ge No.	MQ 78	1	Standa	ard Coun	t		Pi	revious S	Standard			
Standard Density Test No. 04 Sample Obtained From										_					
Theoretical Maximum Density (Rice) Gyratory Density															
	_				1	_	2						1		2
A. Wt.	of sampl	e in Air							A. Wt. o	f Sampl	e in Air	_			
B. Wt. of Canister + Water B. Wt. of sample under water															
C. Wt.	of Canis	ter + Wa	ter + S	Sample					C. Satur	rated Su	rface Dry	y Wt.			
Ter	mperature	e of the \	Nater						D. Volur	me Displ	aced (C	- B)			
D. Wa	ter Corre	ction Fa	ctor						E. Bulk	Specific	Gravity (	(A / D)			
E. Ma	x. Specifi	c Gravity	1						F. Unit \	Weight (	E × 62.24	45)			
	(A + B -								G. Com	paction	Sample 1	Temp.			
F. Ma	x. Unit W	eight (E	× 62.2	45)					Н Ауа	Unit We	iaht				
G. Ave	erage Uni	it Weight	t						II. Avg.	OIIII WE	igiit		_		_
H. Mo	ving Avg.	(Last 5	Tests)			154.3									
						Cut	out Calib	oratio	n Test						
Cutou	t	Dist	tance	Actual	Subr	nersed	SSD Wt	. Wet	Density						
No.	Statio	n fron	n C/L	Dry Wt	. Wt. ii	n Water	in Air		PCF	Nuclear	Gauge I	Readings	Average	W	aiver
1	271+	77 6	LT	2,614.	6 1,	482.3	2,632.5		141.5	140.9	139.2	138.5	139.5		
2	270+		LT	2,496.		426.9	2,504.6	6	144.2	144.3	142.9	141.5	142.9		
3	269+3	32 6	LT	2,574.	6 1,	462.0	2,585.3	3	142.7	143.3	141.9	141.1	142.1		
						PCF	Average		142.8		PCF	Average	141.5		
						Calib	ration Co	orrecti	on _	1.3	PCF				
In-Place Density Measurement															
Lot Lo	cation St	ation	286	6+30	to Static	on37	0+10	_	Distanc	ce from (	Center	12.5 LT			
Lengt	h8,3	80	٧	Vidth	12.5	Quai	ntity Rep	resent	ted11	36.81	_		<u> </u>		
Site	Random	Distanc	ce	R	andom	Dist. from	Wet De	nsity C	Corrected	l % of					
No.	No.	Lot. Be	g. S	tation	No.	Out. Edge	PCF	=	PCF	Standa	ırd	DOT-8?	Wa	iver	
1	0.350	2933.0		15+63	0.720	9.0	140.		141.3	92			l l		
2	0.300	2514.0		11+44	0.790	9.9	141.		142.4	92			I		
3	0.580	4860.4		34+90	0.490	6.1	143.		145.0	94					
4	0.630	5279.4		39+09	0.320	4.0	143.		144.5	94					
5	0.820	6871.6		55+02	0.240	3.0	139.	.2	140.5	91			I		
No more	e than 2 test	s below sp	ec.					Lot	Average	93					

Only 1 test may be 2% below spec. 1 test @ 3% below fails the entire lot.

### SD 311 Page 12

#### SDDOT TABLE OF RANDOM NUMBERS

.53 .74 .23 .99 .67	.61 .32 .28 .69 .84	.94 .62 .67 .86 .24	.98 .33 .74 .19 .95	.47 .53 .53 .38 .09
				.75 .91 .12 .81 .19
.63 .38 .06 .86 .54	.99 .00 .65 .26 .94	.02 .82 .90 .23 .07	.79 .62 .67 .80 .60	
.35 .30 .58 .21 .46	.06 .72 .17 .10 .94	.25 .21 .31 .75 .96	.49 .28 .24 .00 .49	.55 .65 .79 .78 .07
.63 .43 .36 .82 .69	.65 .51 .18 .37 .88	.61 .38 .44 .12 .45	.32 .92 .85 .88 .65	.54 .34 .81 .85 .35
.98 .25 .37 .55 .26	.01 .91 .82 .81 .46	.74 .71 .12 .94 .97	.24 .02 .71 .37 .07	.03 .92 .18 .66 .75
.02 .63 .21 .17 .69	.71 .50 .80 .89 .56	.38 .15 .70 .11 .48	.43 .40 .45 .86 .98	.00 .83 .26 .91 .03
.64 .55 .22 .21 .82	.48 .22 .28 .06 .00	.61 .54 .13 .43 .91	.82 .78 .12 .23 .29	.06 .66 .24 .12 .27
.85 .07 .26 .13 .89	.01 .10 .07 .82 .04	.59 .63 .69 .36 .03	.69 .11 .15 .83 .80	.13 .29 .54 .19 .28
.58 .54 .16 .24 .15	.51 .54 .44 .82 .00	.62 .61 .65 .04 .69	.38 .18 .65 .18 .97	.85 .72 .13 .49 .21
.34 .85 .27 .84 .87	.61 .48 .64 .56 .26	.90 .18 .48 .13 .26	.37 .70 .15 .42 .57	.65 .65 .80 .39 .07
.03 .92 .18 .27 .46	.57 .99 .16 .96 .56	.30 .33 .72 .85 .22	.84 .64 .38 .56 .98	.99 .01 .30 .98 .64
.62 .95 .30 .27 .59	.37 .75 .41 .66 .48	.86 .97 .80 .61 .45	.23 .53 .04 .01 .63	.45 .76 .08 .64 .27
.08 .45 .93 .15 .22	.60 .21 .75 .46 .91	.98 .77 .27 .85 .42	.28 .88 .61 .08 .84	.69 .62 .03 .42 .73
.07 .08 .55 .18 .40	.45 .44 .75 .13 .90	.24 .94 .96 .61 .02	.57 .55 .66 .83 .15	.73 .42 .37 .11 .16
.01 .85 .89 .95 .66	.51 .10 .19 .34 .88	.15 .84 .97 .19 .75	.12 .76 .39 .43 .78	.64 .63 .91 .08 .25
	40 44 50 40 00			
.72 .84 .71 .14 .35	.19 .11 .58 .49 .26	.50 .11 .17 .17 .76	.86 .31 .57 .20 .18	.95 .60 .78 .46 .75
.88 .78 .28 .16 .84	.13 .52 .53 .94 .53	.75 .45 .69 .30 .96	.73 .89 .65 .70 .31	.99 .17 .43 .48 .76
.45 .17 .75 .65 .57	.28 .40 .19 .72 .12	.25 .12 .74 .75 .67	.60 .40 .60 .81 .19	.24 .62 .01 .61 .16
.96 .76 .28 .12 .54	.22 .01 .11 .94 .25	.71 .96 .16 .16 .88	.68 .64 .36 .74 .45	.19 .59 .50 .88 .92
.43 .31 .67 .72 .30	.24 .02 .94 .08 .63	.38 .32 .36 .66 .02	.69 .36 .38 .25 .39	.48 .03 .45 .15 .22
.50 .44 .66 .44 .21	.66 .06 .58 .05 .62	.68 .15 .54 .35 .02	.42 .35 .48 .96 .32	.14 .52 .41 .52 .48
.22 .55 .22 .15 .86	.26 .63 .75 .41 .99	.58 .42 .36 .72 .24	.58 .37 .52 .18 .51	.03 .37 .18 .39 .11
.96 .24 .40 .14 .51	.23 .22 .30 .88 .57	.95 .67 .47 .29 .83	.94 .69 .40 .06 .07	.18 .16 .36 .78 .86
.31 .73 .91 .61 .19	.60 .20 .72 .93 .48	.98 .57 .07 .23 .69	.65 .95 .39 .69 .58	.56 .80 .30 .19 .44
.78 .60 .73 .99 .34	.43 .89 .94 .36 .45	.56 .69 .47 .07 .41	.90 .22 .91 .07 .12	.78 .35 .34 .08 .72
.76 .00 .73 .99 .34	.43 .69 .94 .50 .45	.50 .69 .47 .07 .41	.90 .22 .91 .07 .12	.76 .33 .34 .06 .72
94 37 00 61 56	70 10 22 09 05	95 11 24 76 60	76 49 45 24 60	01 64 18 30 06
.84 .37 .90 .61 .56	.70 .10 .23 .98 .05	.85 .11 .34 .76 .60	.76 .48 .45 .34 .60	.01 .64 .18 .39 .96
.36 .67 .10 .08 .23	.98 .93 .35 .08 .86	.99 .29 .76 .29 .81	.33 .34 .91 .58 .93	.63 .14 .52 .32 .52
.07 .28 .59 .07 .48	.89 .64 .58 .89 .75	.83 .85 .62 .27 .89	.30 .14 .78 .56 .27	.86 .63 .59 .80 .02
.10 .15 .83 .87 .60	.79 .24 .31 .66 .56	.21 .48 .24 .06 .93	.91 .98 .94 .05 .49	.01 .47 .59 .38 .00
.55 .19 .68 .97 .65	.03 .73 .52 .16 .56	.00 .53 .55 .90 .27	.33 .42 .29 .38 .87	.22 .13 .88 .83 .34
.53 .81 .29 .13 .39	.35 .01 .20 .71 .34	.62 .33 .74 .82 .14	.53 .73 .19 .09 .03	.56 .54 .29 .56 .93
.51 .86 .32 .68 .92	.33 .98 .74 .66 .99	.40 .14 .71 .94 .58	.45 .94 .19 .38 .81	.14 .44 .99 .81 .07
.35 .91 .70 .29 .13	.80 .03 .54 .07 .27	.96 .94 .78 .32 .66	.50 .95 .52 .74 .33	.13 .80 .55 .62 .54
.37 .71 .67 .95 .13	.20 .02 .44 .95 .94	.64 .85 .04 .05 .72	.01 .32 .90 .76 .14	.53 .89 .74 .60 .41
.93 .66 .13 .83 .27	.92 .79 .64 .64 .72	.28 .54 .96 .53 .84	.48 .14 .52 .98 .94	.56 .07 .93 .89 .30
				40 40 50 07 44
.02 .96 .08 .45 .65	.13 .05 .00 .41 .84	.93 .07 .54 .72 .59	.21 .45 .57 .09 .77	.19 .48 .56 .27 .44
.02 .96 .08 .45 .65 49 83 43 48 35	.13 .05 .00 .41 .84 82 88 33 69 96	.93 .07 .54 .72 .59 72 .36 .04 .19 .76		.19 .48 .56 .27 .44 82 11 08 95 97
.49 .83 .43 .48 .35	.82 .88 .33 .69 .96	.72 .36 .04 .19 .76	.47 .45 .15 .18 .60	.82 .11 .08 .95 .97
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03 .51 .28 .50 .10 .34	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38 .31 .57 .75 .95 .80	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63 .51 .97 .02 .74 .77	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67 .76 .15 .48 .49 .44	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09 .18 .55 .63 .77 .09
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03 .51 .28 .50 .10 .34	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38 .31 .57 .75 .95 .80	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63 .51 .97 .02 .74 .77	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67 .76 .15 .48 .49 .44	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09 .18 .55 .63 .77 .09
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03 .51 .28 .50 .10 .34 .21 .31 .38 .86 .24	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38 .31 .57 .75 .95 .80 .37 .79 .81 .53 .74	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63 .51 .97 .02 .74 .77 .73 .24 .16 .10 .33	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67 .76 .15 .48 .49 .44 .52 .83 .90 .94 .76	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09 .18 .55 .63 .77 .09 .70 .47 .14 .54 .36
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03 .51 .28 .50 .10 .34 .21 .31 .38 .86 .24	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38 .31 .57 .75 .95 .80 .37 .79 .81 .53 .74	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63 .51 .97 .02 .74 .77 .73 .24 .16 .10 .33	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67 .76 .15 .48 .49 .44 .52 .83 .90 .94 .76	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09 .18 .55 .63 .77 .09 .70 .47 .14 .54 .36
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03 .51 .28 .50 .10 .34 .21 .31 .38 .86 .24 .29 .01 .23 .87 .88	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38 .31 .57 .75 .95 .80 .37 .79 .81 .53 .74 .58 .02 .39 .37 .67	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63 .51 .97 .02 .74 .77 .73 .24 .16 .10 .33 .42 .10 .14 .20 .92	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67 .76 .15 .48 .49 .44 .52 .83 .90 .94 .76 .16 .55 .23 .42 .45	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09 .18 .55 .63 .77 .09 .70 .47 .14 .54 .36 .54 .96 .09 .11 .06
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03 .51 .28 .50 .10 .34 .21 .31 .38 .86 .24 .29 .01 .23 .87 .88 .95 .33 .95 .22 .00	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38 .31 .57 .75 .95 .80 .37 .79 .81 .53 .74 .58 .02 .39 .37 .67	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63 .51 .97 .02 .74 .77 .73 .24 .16 .10 .33 .42 .10 .14 .20 .92 .38 .79 .58 .69 .32	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67 .76 .15 .48 .49 .44 .52 .83 .90 .94 .76 .16 .55 .23 .42 .45 .81 .76 .80 .26 .92	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09 .18 .55 .63 .77 .09 .70 .47 .14 .54 .36 .54 .96 .09 .11 .06
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03 .51 .28 .50 .10 .34 .21 .31 .38 .86 .24 .29 .01 .23 .87 .88 .95 .33 .95 .22 .00 .90 .84 .60 .79 .80 .46 .40 .62 .98 .82	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38 .31 .57 .75 .95 .80 .37 .79 .81 .53 .74 .58 .02 .39 .37 .67 .18 .74 .72 .00 .18 .24 .36 .59 .87 .38 .54 .97 .20 .56 .95	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63 .51 .97 .02 .74 .77 .73 .24 .16 .10 .33 .42 .10 .14 .20 .92 .38 .79 .58 .69 .32 .82 .07 .53 .89 .35 .15 .74 .805 .08 .32	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67 .76 .15 .48 .49 .44 .52 .83 .90 .94 .76 .16 .55 .23 .42 .45 .81 .76 .80 .26 .92 .96 .35 .23 .79 .18 .16 .46 .70 .50 .80	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09 .18 .55 .63 .77 .09 .70 .47 .14 .54 .36 .54 .96 .09 .11 .06 .82 .80 .84 .25 .39 .05 .98 .90 .07 .35 .67 .72 .16 .42 .79
.49 .83 .43 .48 .35 .84 .60 .71 .62 .46 .18 .17 .30 .88 .71 .79 .69 .10 .61 .78 .75 .93 .36 .57 .83 .38 .30 .92 .29 .03 .51 .28 .50 .10 .34 .21 .31 .38 .86 .24 .29 .01 .23 .87 .88 .95 .33 .95 .22 .00 .90 .84 .60 .79 .80	.82 .88 .33 .69 .96 .40 .80 .81 .30 .37 .44 .91 .14 .88 .47 .71 .32 .76 .95 .62 .56 .20 .14 .82 .11 .06 .28 .81 .39 .38 .31 .57 .75 .95 .80 .37 .79 .81 .53 .74 .58 .02 .39 .37 .67 .18 .74 .72 .00 .18 .24 .36 .59 .87 .38	.72 .36 .04 .19 .76 .34 .39 .23 .05 .38 .89 .23 .30 .63 .15 .87 .00 .22 .58 40 .74 .21 .97 .90 .65 .62 .25 .06 .84 .63 .51 .97 .02 .74 .77 .73 .24 .16 .10 .33 .42 .10 .14 .20 .92 .38 .79 .58 .69 .32 .82 .07 .53 .89 .35	.47 .45 .15 .18 .60 .25 .15 .35 .71 .30 .56 .34 .20 .47 .89 .92 .54 .01 .75 .25 .96 .42 .68 .63 .86 .61 .29 .08 .93 .67 .76 .15 .48 .49 .44 .52 .83 .90 .94 .76 .16 .55 .23 .42 .45 .81 .76 .80 .26 .92 .96 .35 .23 .79 .18	.82 .11 .08 .95 .97 .88 .12 .57 .21 .77 .99 .82 .93 .24 .98 .43 .11 .71 .99 .31 .74 .54 .13 .26 .94 .04 .32 .92 .08 .09 .18 .55 .63 .77 .09 .70 .47 .14 .54 .36 .54 .96 .09 .11 .06 .82 .80 .84 .25 .39 .05 .98 .90 .07 .35